CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2998674
Transaction Date	16 Nov 2026, 16:52:23
Site Name	840 - Emirates Auctions
Transaction Number	79304877 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JTNJJXB09C*******
Specification	Imported
Make	Toyota
Model	Scion
Model Year	2012
Color	Silver
Mileage	107447 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED,MISALIGN	مدكار
01.B Paint	BODY REPAIRED REPAINTED,MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION COVERED DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK HEAD INNER FENDER FRAME REPAIRED ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED PORTION RUSTY CRACK DENT	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Other	INNER COMPARTMENT PART SIGN OF BURNING	اخري
03.C Engine Visual Condition	REFITTED , PARTS GTETING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT SEATS EXTRA COVER,REAR HEAD REST MISSING	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	DELAY SHIFTING ,REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Other	SUSPENSION PARTS REFITTED	اخري
08.C Ball Joint	BOOT CUT	مفصل كروي
08.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS RUSTY SIGN OF WATER FLOODED	اخري
09.B Mirror	BOTH SIDE LOOSE INDICATOR LIGHT COVER PORTION CRACK,CENTER VIEW MIRROR FADED	المرايا
09.C AC Condition	NORMAL COOLING	المكيف
09.D Power Window Switch And Glass	RIGHT SIDE NOT WORKING PROPERLY,LEFT SIDE SWITCH PANEL LOOSE	مفتاح النافذه و الزجاج
09.E Audio	NOT WORKING,PANEL LOOSE	صوتيات
09.F Door Panel	PORTION CRACK LOOSE	لوحة بطانة الباب
09.G Gear Shifting Lever	SHIFT LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae