



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 19937548	Plate Category	:
Transaction Date	: 10 JUN 2020 12:33:45	Plate Number	:
Queue Number	: 161	Import Doc. Ref.	: 82964 EA
Chassis Number	: JTHBW1GG3F2082964	Manufacturer/Model	: LEXUS/ES 300
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION	Mileage	: 85248

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TYRES 2018.GETTING WORN OUT.
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok	OK	الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.25 - Body Repainted		أثر صيغ في المركبة
		TRUNK DOOR PORTION REPAINTED.

The Test Certificate Shows the test Result at the time of inspection only.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط