CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2972517
Transaction Date	11 Nov 2026, 17:02:30
Site Name	840 - Emirates Auctions
Transaction Number	88854289 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1C4SDJDT3D*******
Specification	GCC Specification
Make	Dodge
Model	Durango
Model Year	2013
Color	Black
Mileage	122589 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REPAINTED,PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR COVERED PORTION DENT MUDDY	الارضية
01.F Bumper	MISALIGN,GRILL PORTION CRACKED	دعامية
01.G Roof	PORTION REPAINTED	السقف
01.H Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
01.I Trunk	AUTO SWITCH NOT WORKING	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS COVERED MUDDY OILY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	MINOR OIL LEAK OPENREFITTED GETTING RUSTY, SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT BACK COVER PORTION DAMAGED,LOOSE	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	BOTH SIDE COVER PORTION CRACKED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR LEAK	ممتص الصدمات
08.B Arms	BUSHES CRACKED	ازرع
08.C Other	SUSPENSION REFITTED	اخري
08.D Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Other	INNER PARTS GETTING RUSTY ,	اخري
09.B Mirror	CENTER MIRROR PORTION LOOSE	المرايا
09.C AC Condition	OK	المكيف
09.D Audio	MODIFIED	صوتيات
09.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae