



Test Certificate

Site Number 840-EMIRATES AUCTION Plate Code 0

Transaction Number 22731222 Plate Category PRIVATE Transaction Date 05 DEC 2020 11:25:15 Plate Number GLA72042 EA

Queue Number 260063

Chassis Number Manufacturer/Model : PORSCHE/CAYENNE WP1ZZZ92ZGLA72042

Engine Number

Model Year 2016

Import Doc. Ref.

Vehicle Class LIGHT VEHICLE Vehicle Color **BLACK**

Service / Indicator DSC AUCTION

Statement of Vehicle Condition

Defect	Result	Remarks	
Defect	Result	Remarks	
AUTOMATIC TEST:			
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
VISUAL TEST:			
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		FRONT 2016 & 2018	الاطارات الامامية
04.04 - Rear Left And Right Hand Tires		REAR TIRES OLD 2015 & 2016 & RIGHT SIDE PUNCTURE /TEST DRIVE NOT DONE	الاطارات الخلفية
04.07 - Rims		SCRATCHES & WHEEL STUD INCOMPLETE	الرنجات
05 Body			الهيكل
05.02 - Paint		BODY MINOR SCRATCH	الصبغ
05.05 - Bumpers		FRONT BUMPER SUPPORT & LEFT CRASH BOX REPAIRED	الدعامية
05.08 - Chassis (Frame)		FRONT LEFT SIDE MEMBER FRAME OUTER SKIRT&FRONT END JOINT DENT	الشاصية
06 General Items			الاشياء العامة
06.01 - Wiper Blades		WIPER BLADES WORN OUT	ماسحات الزجاج الامامي
06.14 - Transmission Condition		OIL LEAK	حالة ناقل الحركة
07 Remarks			ملاحظات
07.04 - Others		49777 KM BONNET RE-FITTED	ملاحظات اخرى
09 Auction			الفحص الكامل
09.14 - Sign Of Front Accident			أثر حادث في مقدمة المركبة
09.25 - Body Repainted		BODY PORTIONS REPAINTED	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية

Test Certificate









Plate Details: Chassis No: WP1ZZZ92ZGLA72042 Vehicle Make: PORSCHE Vehicle Model: CAYENNE Vehicle Class: Light Vehicle Body Type: STATION Fuel: Benzene Color: Black **Drive Direction:** Dimensions : (H x W x L) --x--x--Current Odometer : 49778 Kms. Origin: Germany Model Year: 2016 Gear Type: Engine Size: 3600 CC Engine No: CXZA002558 Horse Power: 300 Axles No: Cylinders: No Of Doors: 5 No Of Seats: G. V. W. : Empty Weight: 1700 Kgs. 2600 Kgs.

Certificate Number:	5-TAS-2020-13093788		
Inspection Date :	06-12-2020		
Certificate Print Date :	06-12-2020		
Services :	Registration Test		
Vehicle Testing Partner:	Tasjeel		
Vehicle Testing Center :	Tasjeel Emirates Auction		
Total Time Taken: 8 min 57 sec			
Appointment Ref Number			
Start Time: 10:30	End Time: 10:39		
Lane: 01	Token No.: 2		
Attempt: 1	Prints No: 1		

Parameter Readings

Service brake imbalance on front axle

11 %

Service brake imbalance on rear axle 10 %

Parking brake imbalance between LHS and RHS

Vehicle on Petrol CO Reading 0%

Vehicle on Petrol HC

Reading 41 PPM VOL

Inspection Findings

Defects

Issue

Severity

Major

Others (Major)

CHANGE REAR BOTH SIDE & FRONT RIGHT SIDE TIRES CRACKS & OLD 2015 & 2016

Discrepancies	Old Value	New Value	Verified
Doors and Locks Incorrect Number of doors (does not require doc)	5	4	

Inspection Remarks:

FRONT LEFT SIDE MEMBER FRAME OUTER SKIRT&FRONT END JOINT DENT/ FRONT BUMPER SUPPORT & LEFT CRASH BOX REPAIRED

Payment Details Inspection Performed by 59460 Parking Slot No

Payment Method VTP Credit Account Service Name

Transaction Number 13093788 Attempt

Service Fees AED 170 Collected on 06/12/2020 Received by

Raul Canceran Galang

Registration Test

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service. 1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. ᠯ هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص . المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and لقانون السير و المرور 21 لسنة 1995 inspection done-According to Traffic law No., 21 year 1995

