CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2899720 |
| Transaction Date | 26 Oct 2026, 15:55:13 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 73600768 (CC10006) (CC10011) |




Vehicle Details

| | |
|---|---|
| Chassis Number | JN1CC11C67******* |
| Specification | GCC Specification |
| Make | Nissan |
| Model | Tiida |
| Model Year | 2007 |
| Color | White |
| Mileage | N/A Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAINTED PORTION REPAIRED,DENTS SCRATCHES ,PORTION RUSTY FADED | الصبغ |
| 01.B Doors | FRONT LEFT SIDE DAMAGED | أبواب |
| 01.C Rusty | UNDER BODY SUSPENSION PARTS GETTING RUSTY. | صدأ |
| 01.D Floor | UNDER FLOOR PORTION DENT ,MUDDY., | الارضية |
| 01.E Bumper | MISALIGN PORTION DAMAGED | دعامية |
| 01.F Sign of front accident | FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED. | وجود مؤشر لحادث في المقدمة |
| 01.G Sign of back accident | BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED. | وجود مؤشر لحادث في الخلف |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | REAR BOTH SIDE CHASSIS EXTENSION END REPAIRED, GETTING RUSTY | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY | الحالة النظريه للمحرك |
| **04 Seats Condition** | | المقاعد |
| 04.A Seat Condition | DIRTY PORTION LOOSE. | حالة المقاعد |
| **05 Transmission Condition** | | الجير |

| Condition | Remarks | الحالة |
|---|---|---|
| 05.A Gear Box Visual Condition | NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY . | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECKED . | فحص علي الطريق |
| **06 Tires and Rims Condition** | | الاطارات |
| 06.A Front Tyre | EXPIRED CRACKED WORN OUT . | الاطار الامامي |
| 06.B Rear Tyre | EXPIRED CRACKED WORN OUT . | الاطار الخلفي |
| **07 Lights** | | الاضاءة |
| 07.A Head Light | LENS FADED,ALL LIGHT NOT CHECKED | الاضاءة الرئيسية |
| **08 Brake Condition** | | الفرامل |
| 08.A Disc&Drum | PARTS RUSTY . | دسك وطنابير الفرامل |
| **09 Suspension System** | | ممتص الصدمات |
| 09.A Shock Absorber | LEAK . | ممتص الصدمات |
| 09.B Arms | BUSHES CUT . | ازرع |
| **10 Steering Condition** | | المقود |
| 10.A Steering Boot | CUT , | ربلة المقود |
| 10.B Steering Box | OIL LEAK | جهاز المقود |
| **11 Interior Condition** | | الحاله الداخليه |
| 11.A Other | INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED | اخري |
| 11.B AC Condition | NOT CHECKED . | المكيف |
| 11.C Dash Board | PORTION CUT . | لوحة القياده |
| 11.D Sun Visor | LOOSE. | حاجب الشمس |
| 11.E Odometer reading | NOT CHECKED. | قراءة عداد المسافات |
| 11.F Door Panel | WORN OUT PORTION LOOSE. | لوحة بطانة الباب |
| 11.G Steering Wheel and control buttons | WORN OUT . | عجلة القيادة وازرار التحكم |
| 11.H Gear Shifting Lever | KNOB WORN OUT . | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**