CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2870320
Transaction Date	15 Oct 2026, 12:32:18
Site Name	840 - Emirates Auctions
Transaction Number	68751438 (CC10009) (CC10012)

Vehicle Details

Chassis Number	VF39UXFVJ9*******
Specification	GCC Specification
Make	Peugeot
Model	607
Model Year	2009
Color	Unknown
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE , REAR BOTH SIDE NOT OPEN	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	DENT, COVERED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	MISALIGN	صندوق
01.I Fuel Tank	CAP PORTION DAMAGED	خزان الوقود
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.K Vehicle Color	BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS LOWER EDGE DTACHED OPEN DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED OILLEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	OIL LEAKR EFITTED , NOT CHECKED	الحالة النظريه للجير
05.B Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Suspension System		**ممتص الصدمات**
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		**الحاله الداخليه**
09.A Other	INTERIOR PARTS GETTING RUSTY , INTERIOR REFITTED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	LEATHER REPLACED , WORN OUT	لوحة القياده
09.D Roof Ceiling	PORTION LOOSE	بطانه السقف
09.E Door Panel	WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT, ADJUSTIABLE LEVER DAMAGED	عجلة القيادة وازرار التحكم
09.G Sunroof	CURTAIN COVER MISSING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae