CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2915830
Transaction Date	28 Oct 2026, 14:59:39
Site Name	840 - Emirates Auctions
Transaction Number	14752376 (CC10013) (CC10025)



Vehicle Details

Chassis Number	5N1AR2MN6E*******
Specification	Imported
Make	Nissan
Model	Pathfinder
Model Year	2014
Color	White
Mileage	73473 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PAINT PORTION DAMAGED	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED MINOR DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	FRONT SPOT CRACK	زجاج
01.G Bonnet	PORTION REPAIRED REPAINTED	غطاء المحرك
01.H Fuel Tank	DENT / SAFETY BAR BEND	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION RUST PROOFED GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER CRACK	كرسي
03.B Other	INTAKE AIR PIPE PART MISSING	اخري
03.C Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY , MINOR JERKING	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023 CRACK RIGHT SIDE PORTION DAMAGED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES NUT MISSING	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LEFR SIDE LENS FADED DAMAGED LOW BEAM NOT WORKING	الاضاءة الرئيسية
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
11.B AC Condition	OK	المكيف
11.C Roof Light	NOT WORKING PROPERLY	أنارة السقف
11.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.E Gear Shifting Lever	KNOB WORN OUT , LOCK COVER MISSING	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	BOTTLE CAP DAMAGED / OIL MIX WITH WATER	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae