CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899729
Transaction Date	31 Oct 2026, 11:48:35
Site Name	840 - Emirates Auctions
Transaction Number	70644839 (CC10010) (CC10010)



Vehicle Details

Chassis Number	SALGS2EF2G*******
Specification	Imported
Make	Range Rover
Model	Vogue
Model Year	2016
Color	Black
Mileage	104377 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED REFITTED .	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES .	الصبغ
01.C Doors	FRONT RIGHT SIDE SKIRT LOOSE.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS ,RUNNING PARTS POWERTRAIN GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN ,SCRATCHES .	دعامية
01.G Pillars	FRONT PILLAR OUTER COVER CRACKED.	القوائم
01.H Door Handle &Lock	FRONT LEFT DOOR LOCK COVER MISSING.	مقابض الأبواب والأقفال
01.I Fuel Tank	BOTH SIDE DEEP DENT .	خزان الوقود
01.J Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED, NOT VISIBLE PROPERLY, PORTION MUDDY.	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
02.C Chassis Number	VIN AREA LAMINATED .	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	COMPONENT PARTS RUSTY ,SHAKING ,MINOIR OIL LEAK .,UNDER PORTION COVERED , PARTS REFITTED .	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	GET JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED.	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES.	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LEFT SIDE HEAD LIGHT BRACKET REPAIRED . CRACKED.	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER.	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	GET SPONGY	دواسة الفرامل
08.B Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED .	ازرع
10 Interior Condition		الحاله الداخليه
10.A AC Condition	OK	المكيف
10.B Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae