CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2890797
Transaction Date	21 Oct 2026, 14:35:43
Site Name	840 - Emirates Auctions
Transaction Number	88016171 (CC10013) (CC10025)



Vehicle Details

Chassis Number	JTEBU3FJ8J*******
Specification	GCC Specification
Make	Toyota
Model	Prado
Model Year	2018
Color	White
Mileage	351160 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING RUSTY	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR MUDDY DIRTY FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	الارضية
01.F Bumper	PORTION CRACK SCRATCHES	دعامية
01.G Windshield	RIGHT SIDE FRAME STRIP DAMAGED PART MISSING	زجاج
01.H Vehicle Model	LAND CRUISER PRADO	طراز المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS FRAME MUDDY DIRTY PORTION GETTING RUSTY	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	MUDDY , DIRTY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	EXTRA COVER PORTION DAMAGED / REAR FOLDING SEAT NOT WORKING PROPERLY	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MUDDY DIRTY PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Spare Tire &Tools	PART COVER MISSING	الاطار الاحتياطي و العدة
07 Interior Condition		**الحاله الداخليه**
07.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGED , INTRIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
07.B AC Condition	OK	المكيف
07.C Dash Board	LEATHER REPLACED	لوحة القياده
07.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
07.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.F Gear Shifting Lever	KNOB WOR OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae