

Queue Number

2811323

Transaction Date

29 Sep 2026, 13:23:26

Site Name

840 - Emirates Auctions

Transaction Number

53100919 (CC10010) (CC10010)



Vehicle Details

Chassis Number	5XXGT4L3XG*****
Specification	Imported
Make	Kia
Model	Optima
Model Year	2016
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED DWNTS SCRATCHES , PORTION RUSTY MUDDY FADED.	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION MUDDY DENT	الارضية
01.E Bumper	MISALIGN PORTION DAMAGE SCRATCH.	دعامية
01.F Bonnet	REFITTED,	غطاء المحرك
01.G Door Handle &Lock	FRONT LEFT OUTER HANDLE COVER MISSING	مقابض الأبواب والأقفال
01.H Sign of front accident	FRONT BUMPER FRAME FENDER FRAME BULKHEAD RADIATOR SUPPORT REPAIRED.	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED PORTION DENT MUDDY , PORTION MINOR DENT .	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	NOT CHECKED REFITTED COMPONENTS PARTS RUSTY,OIL LEAK.	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED OIL LEAK COMPONENTS PARTS RUSTY.	الحالة النظرية للجير
--------------------------------	---	----------------------

05 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	EXPIRED	الاطار الامامي
05.B Rear Tyre	EXPIRED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADWD ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY	دسك و طنايير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	BUSHES CRACKED	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR CONDITION RUSTY SIGN PF FLOODED	اخرى
09.B AC Condition	NOT CHECKED	المكيف
09.C Odometer reading	NOT CHECKED	قراءة عداد المسافات
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae