



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **23 Oct 2021, 17:57:08**
 Transaction Number **27872414 (CC10006)** Queue Number **312309**



Chassis Number **KL1GM5EU6DB001943**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Chevrolet**
 Model **Malibu**
 Model Year **2013**
 Color **Black**
 Mileage **227333 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	MINOR DENTS , SCRATCHES ON BODY	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR RUST PROOFED	الارضية
01.D Bumper	REAR PORTION CRACKED & MISALIGN	دعامية
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED	كرسي
03.B Engine Condition	OK	حالة المحرك
04 Seats Condition		المقاعد
04.A Seat Condition	OK	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box	OIL LEAK	الجير
05.B Road Test	NOT CHECK	فحص علي الطريق
05.C Gear Box Mount	BUSHES CRACKED	كرسي الجير

DEFECT	REMARKS	
06 Lights	الاضاءة	
06.A Head Light	OK	الاضاءة الرئيسية
06.B Other	OK	اخرى
07 Brake Condition	الفرامل	
07.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
08 Wipers and Arms	المساحات	
08.A Wiper Arm &Blade	OK	ازرع المساحات والشفرات
09 Suspension System	ممتص الصدمات	
09.A Arms	FRONT LOWER ARM BUSHES MINOR CRACKED	ازرع
09.B Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY	
10 Tires and Rims Condition	الاطارات	
10.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
11 Interior Condition	الحالة الداخلية	
11.A Sun Visor	LEFT SIDE MIRROR COVER DAMAGED	حاجب الشمس
11.B AC Condition	OK	المكيف
11.C Mirror	AUTO NOT WORKING	المرايا
11.D Odometer reading	227333 KM	قراءة عداد المسافات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.