

Queue Number

2611864

Transaction Date

03 Aug 2026, 16:25:53

Site Name

840 - Emirates Auctions

Transaction Number

50918829 (CC10021) (CC10011)



Vehicle Details

Chassis Number

WBAZV4100B*****

Specification

GCC Specification

Make

BMW

Model

X5

Model Year

2011

Color

Grey

Mileage

131311 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

FRONT BOTH SIDE FIBER PAINT NOT CHECK

مدكار

01.B Paint

BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES

الصبغ

01.C Doors

FRONT RIGHT,REAR BOTH SIDE REPAINTED PORTION REPAIRED

أبواب

01.D Rusty

UNDER BODY PARTS GETTING RUSTY

صدأ

01.E Floor

FLOOR CHASSIS NOT VISIBLE PROPERLY CHEKCED VISIBLE AREA ONLY

الارضية

01.F Bumper

MISALIGN

دعامية

01.G Bonnet

REPAINTED PORTION REPAIRED,REFITTED

غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis

CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK

الشاسيه

03 Engine Condition

المحرك

03.A Engine Visual Condition

OIL WET,REFITTED,PARTS GETTING RUSTY

الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition

OIL WET REFITTED

الحالة النظرية للجير

04.B Road Test

NOT CHECK

فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre

BOTH SIDE 2023 CRACK

الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط

06 Lights الاضاءة

06.A Head Light	LENS FADED	الاضاءة الرئيسية
-----------------	------------	------------------

07 Interior Condition الحالة الداخلية

07.A Other	CENTER CUP HOLDER SLIDING COVER MISSING	اخرى
07.B Mirror	ADJUSTMENT NOT WORKING PROPERLY,GETTING FADED	المرآيا
07.C AC Condition	LOW COOLING,NOT WORKING PROPERLY,GRILL ADJUSTER MISSING,DISPLAY PANEL NOT WORKING	المكيف
07.D Roof Light	COVER PORTION MISSING	أنارة السقف
07.E Sun Visor	BOTH SIDE MIRROR LIGHT NOT WORKING,LEFT SIDE CASE PORTION CRACKED	حاجب الشمس
07.F Door Panel	PORTION LOOSE	لوحة بطانة الباب
07.G Steering Wheel and control buttons	WORN OUT,ADJUSTMENT NOT WORKING PROPERLY	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae