

Queue Number

2855812

Transaction Date

12 Oct 2026, 09:48:07

Site Name

840 - Emirates Auctions

Transaction Number

60897440 (CC10026) (CC10026)



Vehicle Details

Chassis Number	VF37JNFU4F*****
Specification	GCC Specification
Make	Peugeot
Model	Partner
Model Year	2015
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE & REAR BOTH SIDE REPAINTED PORTION REPAIRED , FRONT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENTS SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PARTS MINOR DENTS	الارضية
01.E Bumper	MISALIGN , PORTION DAMAGE FIX BY SCREW , TOW HOOK COVER MISSING	دعامية
01.F Trunk	REPAINTED PORTION REPAIRED , MISALIGN , NOT OPENING OUTER LOCK PANEL DAMAGE	صندوق
01.G Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED , DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS GETTING RUSTY , MUDDY	الشاسيه
--------------	-------------------------------	---------

03 Engine Condition

المحرك

03.A Other	DRAIN PLUG RETHREAD	اخرى
03.B Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , OPEN REFITTED GETIING RUSTY , MINOR OIL LEAK , MUDDY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
---------------------	------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	ALL SYSTEM NOT CHECK , REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK , MUDDY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	BOTH SIDE SIGN OF CRACK	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHED CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Box	SIGN OF OIL WET	جهاز المقود
09.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE PANEL PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
10.B AC Condition	NOT CHECK , GRILL DAMAGE	المكيف
10.C Audio	CONTROL PANEL BUTTON PORTION FADED	صوتيات
10.D Dash Board	PORTION WORN OUT	لوحة القيادة
10.E Roof Ceiling	FABRIC WORN OUT	بطانه السقف
10.F Sun Visor	BOTH SIDE LOOSE	حاجب الشمس
10.G Odometer reading	NOT CHECK	قراءة عداد المسافات
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB PORTION WORN OUT , DUST COVER DAMAGE	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae