



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>11 Aug 2022, 17:52:19</b>
Transaction Number	<b>80145806 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>KNAKM8117C5078850</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Kia</b>
Model	<b>Mohave</b>
Model Year	<b>2012</b>
Color	<b>--</b>
Mileage	<b>336515 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	NOT CHECKED	المكيف
02.B Dash Board	PORTION DAMAGED	لوحة القيادة
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	NOT CHECKED	حالة الجير النظرى
03.B Road Test	NOT CHECKED	فحص علي الطريق
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Paint	BODY PORTION REPAIRED REPAINTED .MINOR DNETS SCRATCHES . BODY COLOR WHITE	الصبغ
04.B Roof	HAVE HOLE	السقف
<b>05 Chassis Condition</b>		<b>الشاصي</b>
05.A Chassis	OK	الشاسيه

DEFECT	REMARKS	
<b>06 Lights</b>		الاضاءة
06.A Other	BATTERY WEAK, NOT CHECKED	اخرى
<b>07 Engine Condition</b>		المحرك
07.A Visual Engine Condition	OIL LEAK,NOT START	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.