

Queue Number	2810722	Transaction Date	28 Sep 2026, 16:55:20
Site Name	840 - Emirates Auctions	Transaction Number	55275042 (CC10010) (CC10011)



Vehicle Details

Chassis Number	3LN6L2G94F*****
Specification	GCC Specification
Make	Lincoln
Model	MKZ
Model Year	2015
Color	Silver
Mileage	109828 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.B Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED , REAR RIGHT SIDE REFITTED	أبواب
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA .	الارضية
01.E Bumper	MISALIGN , SCRATCHES PORTION FADED , FRONT RIGHT SIDE REFLECTOR LOOSE , CUT	دعامة
01.F Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COVERED ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY DOOR POST STICKER.	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED ,MINOR OIL LEAK . ABNORMAL NOISY ,SHAKING.	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED ,MINOR OIL LEAK . GET JERKING.	الحالة النظرية للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Other	SUSPENSION PARTS REFITTED ,NOISY WHILE DRIVE .	اخرى
08 Interior Condition		الحالة الداخلية
08.A Other	CENTER CONSOLE BOX COVER PORTION CRACK/INTERIOR PARTS GETTING MINOR RUSTY.	اخرى
08.B Mirror	BOTH SIDE VIEW MIRROR HOUSING SCRATCHES	المرآيا
08.C AC Condition	OK , REAR GRILL LOOSE	المكيف
08.D Floor Matting	EXTRA PLASTIC COVER	فرش الأرضية
08.E Sun Visor	RIGHT SIDE GLASS MIRROR DAMAGE	حاجب الشمس
08.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Engine Start Button	REMOTE PORTION WORN OUT FIX BY TAPE	زر تشغيل المحرك
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae