

Queue Number

2877716

Transaction Date

19 Oct 2026, 12:12:52

Site Name

840 - Emirates Auctions

Transaction Number

44262020 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JN1CC13C58*****
Specification	GCC Specification
Make	Nissan
Model	Tiida
Model Year	2008
Color	Yellow
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT .	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL ,QUARTER PANEL ,SPARE WHEEL HOUSING REPAIRED,DENT .	وجود مؤشر لحادث في الخلف
01.G Vehicle Color	GOLDEN	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS END LOWER SKIRT DENT ,REAR EXTENSION END DENT , GETING RUSTY.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	EXPORED DAMAGED	الاطار الامامي
05.B Rear Tyre	EXPIRWD DAMAGED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
06.B Tail Light	PORTION CRACKED	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخرى
10.B Dash Board	PORTION DAMAGED	لوحة القيادة
10.C Roof Ceiling	PORTION LOOSE.	بطانة السقف
10.D Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae