



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>20 Mar 2022, 11:19:13</b>
Transaction Number	<b>67992963 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTB31UJ75W3009755</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Land Cruiser</b>
Model Year	<b>1998</b>
Color	<b>Silver</b>
Mileage	<b>434102 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Wipers and Arms</b>		<b>المساحات</b>
01.A Wiper Arm &Blade	NOT WORKING	ازرع المساحات والشفرات
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Power Window Switch	LEFT SIDE POWER WIND NOT WORKING	مفتاح النافذه
02.B Steering Wheel and control buttons	LOOSE	عجلة القيادة وازرار التحكم
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES, BODY PORTION RUSTY	الصبغ
03.B Floor	FLOOR RUSTY REPAIRED ,STILL MAJOR RUSTY HOLE , BOTH SIDE RUNNING BOARD RUSTY , REPAIRED	الارضية
03.C Pillars	BOTH SIDE RUSTY REPAIRED	القوائم
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Leaf Spring	FRONT BOTH SIDE BUSHES WORN OUT	
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Steering Oil	MINOR OIL LEAK	زيت المقود

DEFECT	REMARKS	
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Road Test	NOT CHECKED	فحص علي الطريق
06.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظرى
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	OK&CHASSIS FRAME SANDBLAST AND PAINTED,PORTION MINOR RUSTY	الشاسيه
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2017/2020 WORN OUT	الاطار الخلفي
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Revers Light	NOT WORKING	نور الرجوع للخلف
<b>10 Seats Condition</b>		<b>المقاعد</b>
10.A Seat Condition	DRIVER SEAT DAMGED	حالة المقاعد
<b>11 Engine Condition</b>		<b>المحرك</b>
11.A Visual Engine Condition	OK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.