

Queue Number 2887666

Transaction Date 20 Oct 2026, 14:40:50

Site Name
840 - Emirates AuctionsTransaction Number
70235390 (CC10013) (CC10011)

Vehicle Details

Chassis Number	5N1DR2BM7L*****
Specification	Imported
Make	Nissan
Model	Pathfinder
Model Year	2020
Color	Black
Mileage	91096 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH REAR RIGHT SIDE REPAINTED PORTION REPAIRED,FRONT RIGHT REFITTED REAR RIGHT REPLACED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION RUSTY	الصبغ
01.C Doors	FRONT LEFT,RAER RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED DENT	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.G Bonnet	REPAINTED REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE A/PILLAR PORTION DENTS,C/PILLAR REPAINTED PORTION REPAIRED	القوائم
01.I Other	VEHICLE WHILE DRIVE SUSPENSION NOISY	اخرى
01.J Trunk	REPAINTED PORTION REPAIRED,REFITTED	صندوق
01.K Fuel Tank	SAFETY BAR DENT	خزان الوقود
01.L Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD , INNER FENDER FRAME REPAIRED , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.M Sign of back accident	BACK PANEL QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE & REAR RIGHT SIDE REPAIRED DENT BEND GETTING RUSTY / RUST PROOFED / SANDBLAST	الشاسيه
--------------	--	---------

Condition	Remarks	الحالة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL PAN DENT , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Exhaust System		نظام العادم
04.A Other	DENT	اخرى
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , OIL PAN DENT , OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Other	SUSPENSION PARTS REFITTED	اخرى
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF WATER FLOODED	اخرى
09.B AC Condition	OK	المكيف
09.C Dash Board	MINOR SCRATCHES	لوحة القيادة
09.D Roof Ceiling	PORTION SIGN OF BEND	بطانه السقف
09.E Air Bag	LEFT SIDE DAMAGED	وسائد هوائية
09.F Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات
09.G Engine Start Button	FADED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae