

Queue Number 2772755

Transaction Date 19 Sep 2026, 12:59:46

Site Name
840 - Emirates AuctionsTransaction Number
45497560 (CC10010) (CC10011)

Vehicle Details

Chassis Number SJAAB1ZVXH*****
Specification GCC Specification
Make Bentley
Model Bentayga
Model Year 2017
Color Black
Mileage 168080 Km
Fuel Type Petrol
Transmission Type
No. Of Cylinders 12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE PORTION REPAIRED REPAINTED , REAR LEFT SIDE OUTER SKIRT MISSING	مكدار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION GETTING FADED RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR COVERED DIRTY MUDDY MINOR DENT.	الارضية
01.E Bumper	MISALIGN,PORTION CRACK,REFLECTOR PORTION CRACK,LOGO GETTING FADED	دعامية
01.F Windshield	FRONT SPOT CRACK	زجاج
01.G Bonnet	STAY SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED MISALIGN ,INNER SWITCH PANEL LOOSE,LUGGAGE SHADE MISSING,NUMBER PLATE PANEL CRACKED,LOGO GETTING FADED	صندوق
01.I Sign of front accident	FRONT ASSEMBLY REFITTED , BOTH SIDE APPRON AREA DENT BEND.	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL , QUARTER PANEL REPAIRED.	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	REAR LEFT SIDE CHASSIS BEND OPEN DETACH PORTION CRACK / FRONT MUDDY.	الشاسيه
--------------	--	---------


03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET, REFITTED , PARTS GETTING RUSTY,RATCHLING NOISY.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد



Condition	Remarks	الحالة
04.A Seat Condition	FRONT SEATS BACK COVER PORTION LOOSE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	PORTION BEND / CUT REWELDED.	اخرى
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , JERKING , PARTS GETTING RUSTY , MINOR OIL LEAK.	الحالة النظرية للجير
06.B Road Test	NOT CHECKED .	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2020,RIGHT 2021 CRACKED EXPIRED	الاطار الخلفي
07.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Other	ELECTRICAL SYSTEM FAULT	اخرى
08.C Warning Light	WARNING LIGHT,MESSAGE ON DISPLAY	ضوء تحذير
08.D Revers Light	NOT WORKING	نور الرجوع للخلف
09 Brake Condition		الفرامل
09.A Brake Pedal	GETTING SPONGY,.	دواسة الفرامل
09.B Disc&Drum	GETTING RUSTY.	دسك و طنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Suspension Subframe	REFITTED .	ممتص الصدمات ازرع
10.B Shock Absorber	AIR SUSPENSION NOT WORKING.	
10.C Arms	BUSHES CRACKED .	
11 Steering Condition		المقود
11.A Steering Boot	RIGHT SIDE INNER BOOT LOOSE.	ربلة المقود
12 Interior Condition		الحالة الداخليه
12.A Other	CENTER CONSOLE BOX COVER MINOR WORN OUT (INTERIOR PARTS REFITTED GETTING RUSTY)	اخرى
12.B AC Condition	OK	المكيف
12.C Dash Board	LEATHER REPLACED PORTION LOOSE	لوحة القيادة
12.D Roof Ceiling	PORTION LOOSE	بطانه السقف
12.E Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
12.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.G Engine Start Button	GETTING FADED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae