



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Nov 2021, 18:40:07
Transaction Number	98273174 (CC10006)	Queue Number	312309



Chassis Number	JM7BM1SZXG1316322
Engine Number	
Vehicle Class	Car
Manufacturer	Mazda
Model	3
Model Year	2016
Color	Silver
Mileage	122275 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Body</b>		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,BODY DENT,SCRATCHES	الصبغ
01.B Fenders	REAR RIGHT SIDE PORTION REPAINTED&RIGHT RUNNING BOARD REPAINTED, REPAIRED,	مدكار
01.C Doors	RIGHT SIDE DOOR DENT	أبواب
01.D Bumper	FRONT MISALIGN &GRILL CRACKED	دعامية
01.E Floor	UNDER BODY FULLY COVERED	الارضية
<b>02 Chassis Condition</b>		الشاسي
02.A Chassis	OK	الشاسيه
<b>03 Engine Condition</b>		المحرك
03.A Engine Condition	OK	حالة المحرك
<b>04 Transmission Condition</b>		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	OK	الجير
<b>05 Seats Condition</b>		المقاعد

DEFECT	REMARKS	
05.A Seat Belt	OK	حزام الأمان
05.B Seat Condition	OK	حالة المقاعد
<b>06 Wipers and Arms</b>		<b>المساحات</b>
06.A Wiper Arm & Blade	WORNOUT	ازرع المساحات والشفرات
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Head Light	FADED	الاضاءة الرئيسية
<b>08 Interior Condition</b>		<b>الحالة الداخليه</b>
08.A Power Window Switch	REAR LEFT SIDE NOT WORKING FROM MAIN SWITCH	مفتاح النافذه
08.B AC Condition	NOT WORKING	المكيف
08.C Other	GEAR LEVER LOCK BUTTON COVER MISSING	اخرى
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Arms	FRONT LOWER ARM BUSHES MINOR CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.