

Queue Number

2846369

Transaction Date

08 Oct 2026, 16:49:29

Site Name

840 - Emirates Auctions

Transaction Number

47175964 (CC10013) (CC10011)



Vehicle Details

Chassis Number

WBAHS7103H*****

Specification

GCC Specification

Make

BMW

Model

X1

Model Year

2017

Color

White

Mileage

111125 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE ,REAR LEFT REPAINTED PORTION REPAIRED,FRONT RIGHT SIGN OF REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED,REAR LEFT REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COMPLETELY COVERED DIRTY / FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	الارضية
01.F Bumper	MISALIGN PORTION CRACK,BOTH SIDE REFLECTOR CRACKED	دعامية
01.G Windshield	PORTION CRACK	زجاج
01.H Bonnet	REPAIRED REPAINTED REFITTED,STAY SHOCK NOT WORKING	غطاء المحرك
01.I Other	FRONT ASSEMBLY REFITTED	اخرى
01.J Trunk	SWITCH GETTING MELTED WORN OUT	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED DIRTY MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET , OPEN REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LEFT SIDE LENS GETTING FADED	الاضاءة الرئيسية
06.B Tail Light	LEFT SIDE PORTION GETTING CRACK	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Hand Brake	SWITCH PORTION CRACK	فرامل اليد
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Other	SUSPENSION PARTS REFITTED	اخرى
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY ,CENTER CONSOLE BOX COVER BRACKET DAMAGED,CUP HOLDER SLIDING COVER PORTION DAMAGED STUCK,CONTROLLING SWITCH PANEL GETTING FADED	اخرى
09.B AC Condition	OK	المكيف
09.C Power Window Switch And Glass	REAR BOTH SIDE QUARTER GLASS BEADING CRACKED	مفتاح النافذه و الزجاج
09.D Roof Ceiling	PORTION LOOSE	بطانه السقف
09.E Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09.H Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae