CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906032
Transaction Date	30 Oct 2026, 14:54:56
Site Name	840 - Emirates Auctions
Transaction Number	18129488 (CC10010) (CC10011)



Vehicle Details

Chassis Number	1FMCU92G99*******
Specification	GCC Specification
Make	Ford
Model	Escape
Model Year	2009
Color	Blue
Mileage	218057 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.E Roof	DEEP DENT	السقف
01.F Bonnet	REFITTED	غطاء المحرك
01.G Door Handle &Lock	FRONT LEFT SIDE DOOR OUTER HANDLE NOT WORKING	مقابض الأبواب والأقفال
01.H Fuel Tank	FUEL LEAK DRIPPING.	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSTY PORTION DENT PORTION MUDDY .	الشاسيه
02.B Chassis Number	VIN AREA GETTING RUSTY.	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION CRACK WORN OUT	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED .	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .,	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE CRACKED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CUT	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY.	اخري
11.B Mirror	CENTER FADED	المرايا
11.C AC Condition	NOT CHECK,GRILL PORTION LOOSE	المكيف
11.D Dash Board	PORTION CRACK	لوحة القياده
11.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.