



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	26 Jun 2022, 17:43:17
Transaction Number	54209107 (CC10006)	Queue Number	312309



Chassis Number	55SWF8HB0HU202183
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	C 63 AMG
Model Year	2017
Color	Black
Mileage	120038 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
01.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
02 Interior Condition		الحاله الداخليه
02.A AC Condition	OK	المكيف
02.B Power Window Switch	FRONT RIGHT SIDE NOT WORKING FRONT CENETR SWITCH	مفتاح النافذه
02.C Sunroof	NOT WORKING PROPERLY	فتحت سقف
02.D Steering Wheel and control buttons	WORN OUT COVER LOOSE	عجلة القيادة وازرار التحكم
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	OK	حالة الجير النظري
04 Engine Cooling System		نظام تبريد المحرك
04.A Coolant tank	SIGN OF COOLINT PIPE LEAK	خزان التبريد
05 Seats Condition		المقاعد

DEFECT	REMARKS	
05.A Seat Belt	REAR LEFT SIDE NOT WORKING	حزام الأمان
06 Body		جسم المركبة
06.A Fenders	FRONT BOTH SIDE PORTION REPAINTED,REFITTED	مدكار
06.B Bonnet	MODIFIED,REFITTED,HAVE STICKER	غطاء المحرك
06.C Sign of front accident		وجود مؤشر لحادث في المقدمة
06.D Other	FROTN BUMPER BULK HED REFITTED	اخرى
06.E Floor	UNDER FLOOR FULLY COVERED CHECKED VISIBLE AREA OK	الارضية
06.F Paint	PORTION REPAINTED ,MINOR DENTS SCRATCHES ON BODY	الصبغ
06.G Bumper	FRONT BUMPER RADIATOR ASSMEBLY REFITTED	دعامية
07 Engine Condition		المحرك
07.A Visual Engine Condition	OK	حالة المحرك النظري
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CRACKED	ازرع
09 Chassis Condition		الشاسي
09.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.