CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2965720
Transaction Date	09 Nov 2026, 16:33:17
Site Name	840 - Emirates Auctions
Transaction Number	87593198 (CC10026) (CC10026)



Vehicle Details

Chassis Number	WVGAM27L88*******
Specification	GCC Specification
Make	Volkswagen
Model	Touareg
Model Year	2008
Color	Grey
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE FIBER PAINT NO CHECK & REAR LEFT SIDE PORTION REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	BOTH SIDE LEFT REPAINTED PORTION & REAR PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY , SIGN OF FLOODED	صدأ
01.E Floor	UNDER FLOOR PARTS PORTION COVER , MINOR DENT	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.G Trunk	PLATE NUMBER LIGHT BOTH SIDE DAMAGE	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY / OK	الشاسيه
02.B Chassis Number	DOOR POST MANUFACTURE STICKER PORTION FADED	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK , DRIVER SEAT PLAY	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECK , GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 EXPIRED	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Steering Condition		المقود
09.A Steering Oil	MINOR OIL LEAK	زيت المقود
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER DAMAGE , INTERIOR PARTS GETTING RUSTY	اخري
10.B Mirror	RIGHT SIDE VIEW MIRROR DAMAGE	المرايا
10.C AC Condition	NOT CHECK	المكيف
10.D Dash Board	PORTION WORN OUT	لوحة القياده
10.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.F Door Panel	PORTION DAMAGE	لوحة بطانة الباب
10.G Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	PORTION DAMAGE	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae