

Queue Number

2891410

Transaction Date

26 Oct 2026, 14:20:02

Site Name

840 - Emirates Auctions

Transaction Number

13727850 (CC10010) (CC10010)



Vehicle Details

Chassis Number

WDDZF4KBXH*****

Specification

Imported

Make

Mercedes

Model

E 300

Model Year

2017

Color

Silver

Mileage

120032 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	LEFT SIDE FRONT & REAR REPAINTED PORTION REPAIRED FRONT LEFT REFITTED .	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH DOORS REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS POWERTRAIN ,RUNNING PARTS RUSTY. SIGN OF FLOODED.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN SCRATCHES .	دعامية
01.G Bonnet	PORTION REPAINTED	غطاء المحرك
01.H Sign of front accident	FRONT ASSEMBLY REFITTED ,LEFT FENDER INNER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident	QUARTER PANEL ,WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب
01.J Vehicle Color	GRAY.	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA ,PORTION DENT .	الشاسيه
02.B Other	NEED TO REMOVE FRONT BOTH SIDE FENDER COVER UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,COOLANT MIXED WITH OIL .	الحالة النظرية للمحرك
------------------------------	--	-----------------------

Condition	Remarks	الحالة
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الخلفي
05.C Rims Condition	DENT SCRATCHES.	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	NOT CHECKED.	المكيف
09.C Floor Matting	CENTER CONSOLE BOX COVER CRACKED.	فرش الأرضيه
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	OIL MIXED WITH COOLANT .	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae