



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jul 2022, 13:15:47
Transaction Number	87180797 (CC10006)	Queue Number	312309



Chassis Number	WBAKB8104BC345188
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	750LI
Model Year	2011
Color	Black
Mileage	238428 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	REFITTED	حالة الجير النظري
01.C Gear Box Mount	MOUNT RUBBER CARCKED	كرسي الجير
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
02.B Rims Condition	RIMS HAVE DENT SCRATCHES	حالة الجنوط
02.C Front Tyre	BOTH SIDE 2020	الاطار الامامي
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Mount	MOUNT RUBBER CARCKED	كرسي
03.B Visual Engine Condition	MINOR OIL LEAK REFITTED,SHAKING	حالة المحرك النظري
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
04.C Other	STABLIZER LINK BOOT CUT	اخرى

DEFECT	REMARKS	
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
<b>06 Interior Condition</b>		<b>الحاله الداخليه</b>
06.A AC Condition	OK	المكيف
06.B Roof Ceiling	PORTION LOOSE	بطانه السقف
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Paint	BODY PORTION REPAINTED,MINOR DENT,SCRATCHES	الصبغ
07.B Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA, COVER PORTION DAMAGED	الارضيه
<b>08 Chassis Condition</b>		<b>الشاصي</b>
08.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.