


Condition

TEST CERTIFICATE

Site Number 840-Emirates Auctions Transaction Date 13 May 2022, 11:51:49

Transaction Number 77567159 (CC10006) Queue Number 312309



Chassis Number **SALWA2EF2EA303050**

Engine Number

Vehicle Class Car

Manufacturer Range Rover

Model Sport
Model Year 2014
Color White

Mileage **161245 Km**

Fuel Type P
No. Of Cylinders 8

Specification GCC Specification

Petrol

DEFECT REMARKS

Of Interior Condition

O1.A MirrorLEFT SIDE FOLDING NOT WORKINGالمراياO1.B Roof CeilingLOOSEبطانه السقفO1.C AC ConditionOKفيف

 02 Transmission Condition

فحص علي الطريق NOT CHECK فحص علي الطريق O2.B Visual Gear Box MINOR OIL LEAK

الاطارات 03 Tires and Rims Condition

 03.A Rear Tyre
 BOTH SIDE 2020

 03.B Front Tyre
 BOTH SIDE 2020

O4 Engine Condition المحرك

حالة المحرك النظري OIL LEAK

ممتص الصدمات ممتض الصدمات

ازرع FRONT LOWER ARM BUSH CRACKED

 06 Body
 چسم المركبة

DEFECT	REMARKS	
06.A Paint	BODY MINOR DENT ,SCRATCHES	الصبغ
06.B Floor	UNDER BODY FULLY COVERED&VISIBLE AREA CHECK ONLY	الارضية
07 Chassis Condition		الشاصي
07.A Chassis	ОК	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.