



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	02 Jan 2022, 18:07:39
Transaction Number	39629932 (CC10006)	Queue Number	312309



Chassis Number	WBAXG5C50CDY30258
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	528 I
Model Year	2012
Color	White
Mileage	145304 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Air Bag	BOTH SIDE AIR BAG DAMAGED,MISSING	وسائد هوائية
01.B AC Condition	OK & FRONT , REAR VENT GRILL DAMAGED	المكيف
01.C Other	CENTER CONSOLE BOX COVER LEATHER WORN OUT	اخرى
01.D Roof Ceiling	LOOSE	بطانه السقف
01.E Steering Wheel and control buttons	STEERING WHEEL COVER LOOSE	عجلة القيادة وازرار التحكم
01.F Door Panel	REAR BOTH SIDE MINOR CRACKED	لوحة بطانة الباب
02 Engine Condition		المحرك
02.A Engine Condition	OIL LEAK,SHAKING ,ABNORMAL NOISY	حالة المحرك
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Gear Box	OIL LEAK	الجير
04 Lights		الاضاءة
04.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04.B Head Light	ALL LIGHT WORKING	الاضاءة الرئيسية

DEFECT	REMARKS	
05 Body		جسم المركبة
05.A Fenders	REAR BOTH SIDE REPAINTED & RIGHT SIDE PORTION REPAIRED	مدكار
05.B Doors	REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
05.C Trunk	REPAINTED,PORTION REPAIRED	صندوق
05.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
05.E Sign of side accident		وجود مؤشر لحادث في الجانب
05.F Other	REAR RIGHT SIDE QUATER PANEL REPAIRED	اخرى
05.G Bumper	REPAINTED	دعامية
05.H Floor	UNDER FLOOR COVERED&UNDER ENGINE COVER DAMAGED	الارضية
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
06.C Rims Condition	RIMS HAVE DENT , SCRATCHES	حالة الجنوط
07 Chassis Condition		الشاسي
07.A Chassis	REAR RIGHT SIDE CHASSIS ,CHASSIS EXTENSION REPAIRED	الشاسيه
08 Seats Condition		المقاعد
08.A Seat Belt	OK	حزام الأمان
08.B Seat Condition	BACK SEAT STORE COVER DAMAGED	حالة المقاعد
09 Wipers and Arms		المساحات
09.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Transfer Certificate :	66060381
Chassis No :	WBAXG5C50CDY30258
Vehicle Make :	BMW
Vehicle Model :	528 I
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	145308 Kms. x
Origin :	Germany
Model Year :	2012
Gear Type :	Automatic
Engine Size :	2000 CC
Engine No :	NIL
Horse Power :	240
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1900 Kgs. 2400 Kgs.

Certificate Number :	5-TAS-2022-15850315
Inspection Date :	09-01-2022
Certificate Print Date :	09-01-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	7 min 50 sec
Appointment Ref Number :	--
Start Time :	16:03
End Time :	16:11
Lane :	01
Token No. :	210
Attempt :	2
Prints No :	2

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)

101444 KM	7208 L	11677 AED	17.3 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks:

PREVIOUS KM 208287 / RIGHT SIDE QUARTER PANEL AND WHEEL ARC, REAR RIGHT SIDE MEMBER OUTER SKIRT. REPAIRED. ENGINE OIL MINOR LEAK. CLEANED.



Odometer Record

Replace Events Date

09/01/2022

Payment Details

Inspection Performed by 37084	Payment Method Cash	Transaction Number 15850315	Service Fees AED 70 Collected on 09/01/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

