CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2944935
Transaction Date	04 Nov 2026, 16:47:00
Site Name	840 - Emirates Auctions
Transaction Number	83186371 (CC10009) (CC10011)



Vehicle Details

Chassis Number	JTMHU09J7E*******
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2014
Color	Silver
Mileage	205183 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	MINOR DENTS SCRATCHES ON BODY,PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR CHASSIS THICK RUST PROOFED	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
01.E Roof	LEFT SIDE ROOF RAIL PART MISSING	السقف
01.F Trunk	STAY SHOCK NOT WORKING	صندوق
01.G Sign of front accident	FRONT BUMPER BULK HEEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED,OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY, MINOR SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	COVER PORTION WORN OUT,REAR MIDDLE NECK REST MISSING	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	PARTS GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

CAR CHECK

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACKED LOW AIR	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACKED LOW AIR	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Other	COOL BOX COVER PORTION DAMAGED, INNER PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
09.B AC Condition	NO COOLING,FRONT BLOWER NOT WORKING PROPERLY	المكيف
09.C Roof Light	FRONT PANEL LOOSE	أنارة السقف
09.D Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING FROM MAIN SWITCH	مفتاح النافذه و الزجاج
09.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae