



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **09 Aug 2022, 14:49:02**  
 Transaction Number **38813149 (CC10006)** Queue Number **312309**



Chassis Number **MNTBC2C93E6001257**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Nissan**  
 Model **Tiida**  
 Model Year **2014**  
 Color **Red**  
 Mileage **244184 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED & REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	أبواب
01.D Fenders	FRONT BOTH SIDE PORTION REPAINTED & REAR BOTH SIDE PORTION REPAIRED, REPAINTED	مدكار
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.B AC Condition	NOT COOLING	المكيف
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	JERKING	حالة الجير النظري
<b>04 Steering Condition</b>		<b>المقود</b>
04.A Axle	RIGHT SIDE BOOT LEAK	اكسلات

DEFECT	REMARKS	
04.B Tie Rod End	BOOT CRACKED	مؤخرة الرودادات
<b>05 Lights</b> <span style="float: right;">الاضاءة</span>		
05.A Head Light	LENS FADED	الاضاءة الرئيسية
<b>06 Chassis Condition</b> <span style="float: right;">الشاصي</span>		
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>07 Tires and Rims Condition</b> <span style="float: right;">الاطارات</span>		
07.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
<b>08 Engine Condition</b> <span style="float: right;">المحرك</span>		
08.A Smoke	WHITE SMOKE	دخان
08.B Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
<b>09 Suspension System</b> <span style="float: right;">ممتص الصدمات</span>		
09.A Ball Joint	BOOT CRACKED	مفصل كروي
09.B Arms	LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.