



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Sep 2022, 10:46:34
Transaction Number	38118399 (CC10009)	Queue Number	592593



Chassis Number	JTDKW9D35DD526199
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Yaris
Model Year	2013
Color	White
Mileage	304557 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Other	INTERIOR DUSTY	اخري
01.B AC Condition	NOT WORKING	المكيف
01.C Door Panel	PORTION LOOSE,DAMAGED	لوحة بطانة الباب
01.D Power Window Switch	MAIN SWITCH PANEL POWER WINDOW LOCK BUTTON DAMAGED	مفتاح النافذه
02 Body		جسم المركبة
02.A Paint	BODY PROTION REPAIRED REPAINTED MINOR DENTS SCRATCHES ON BODY , DUSTY , PORTION FADED	الصبغ
02.B Bumper	MISALIGN,PORTION DAMAGED	دعامية
02.C Sign of front accident		وجود مؤشر لحادث في المقدمة
02.D Sign of back accident		وجود مؤشر لحادث في الخلف
02.E Floor	WASH UNDER FLOOR CHASSIS TOO MUDDY	الارضية
03 Seats Condition		المقاعد
03.A Seat Condition	DRIVER SEAT PORTION DAMAGED & REAR SEATS HAVE SEAT COVER	حالة المقاعد
04 Transmission Condition		الجير

DEFECT	REMARKS	
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
04.C Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2019 MINOR CRACKED	الاطار الخلفي
06 Engine Condition		المحرك
06.A Mount	MOUNT RUBBER CUT	كرسي
06.B Visual Engine Condition	OIL LEAK,SHAKING	حالة المحرك النظري
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CUT	ازرع
08.B Shock Absorber	REAR SHOCK LEAK	ممتص الصدمات
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Chassis Condition		الشاصي
09.A Chassis	UNDER FLOOR CHASSIS TOO MUDDY . CHECKED VISIBLE AREA ONLY OK	الشاسيه
10 Lights		الاضاءة
10.A Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
10.B Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.