





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19937559	Plate Category	: PRIVATE
Transaction Date	: 10 JUN 2020 12:36:16	Plate Number	: 0039 EA
Queue Number	: 184596	Import Doc. Ref.	:
Chassis Number	: 1ZVBP8CF6D5220039	Manufacturer/Model	: FORD/MUSTANG
Engine Number	:	Model Year	: 2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE-BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
03 Brake System		تنظيم الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
	BRAKE ROTORS RUSTY	
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
	ALL TIRES DOT 2017	
04.07 - Rims		الرنجات
	SCRATCHES	
04.08 - Spare Tires		الاطار الاحتياطي
	MISSING	
05 Body		الهيكل
05.02 - Paint		الصبغ
	BODY DENT,SCRATCHES	
05.03 - Doors		الابواب
	BONNET MODIFIED/ REPAIRED/ RIGHT DOOR REPAIRED	
05.04 - Fenders		المدكار
	FRONT LEFT FENDER REPLACED/ FENDERS REFITTED	
05.05 - Bumpers		الدعامية
	BUMPER REPAIRED	
05.08 - Chassis (Frame)		الشاصية
	FRONT LEFT SIDE MEMBER REPAIRED/ RIGHT SIDE MEMBER END DENT	
06 General Items		الاشياء العامة
06.10 - Mirrors Side View		المرايا الجانبية
	RIGHT MIRROR ASSY LOOSE / MALFUNCTION	
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
	INTERIOR PARTLY WORN OUT	
06.14 - Transmission Condition		حالة ناقل الحركة
	OK	
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
	OK	
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
	293410 KMS/ ENGINE OIL STAIN	
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19937559	Plate Category	: PRIVATE
Transaction Date	: 10 JUN 2020 12:36:16	Plate Number	: 0039 EA
Queue Number	: 184596	Import Doc. Ref.	:
Chassis Number	: 1ZVBP8CF6D5220039	Manufacturer/Model	: FORD/MUSTANG
Engine Number	:	Model Year	: 2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE-BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.24 - Digital Display Damaged/Warning Lights	TYRE PRESSURE LIGHT ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		

Test Certificate

PASS



Vehicle
Registration



RTA

Plate Details :	--
Chassis No :	1ZVBP8CF6D5220039
Vehicle Make :	FORD
Vehicle Model :	MUSTANG
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	293413 Kms.
Origin : United States	Model Year : 2013
Gear Type : --	
Engine No : d522039	Engine Size : 5000 CC
Axles No : 2	Horse Power : 420
No Of Doors : 2	
G. V. W. : 2000 Kgs.	Cylinders : 8
	No Of Seats : 4
	Empty Weight : 1641 Kgs.

Certificate Number :	5-TAS-2020-12030770
Inspection Date :	16-06-2020
Certificate Print Date :	16-06-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	13 min 5 sec
Appointment Ref Number :	--
Start Time : 15:38	End Time : 15:51
Lane : 01	Token No. : 4
Attempt : 1	Prints No : 1

Carbon footprint



ton CO2

12+

Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)



29341 KM

Distance per
year

3020 L

Fuel consumed
per year

4893 AED

Fuel cost per
year

7.3 ton

Carbon footprint
per year

Parameter Readings

Service brake imbalance on
front axle
2 %

Service brake imbalance on
rear axle
11 %

Parking brake imbalance
between LHS and RHS
15 %

Vehicle on Petrol CO Reading
0 %

Vehicle on Petrol HC Reading
43 PPM VOL

Inspection Remarks: front left side frame member end /bulkhead/bumper support frame repaired

Payment Details

Inspection Performed by
59460

Payment Method
VTP Credit Account

Transaction Number
12030770

Service Fees
AED 170 Collected on 16/06/2020

Parking Slot No
--

Service Name
Registration Test

Attempt
1

Received by
Raul Canceran Galang

① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

① Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صادرة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

TASJEEL
تسجيل