



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	17 Apr 2022, 09:44:20
Transaction Number	95741913 (CC10008)	Queue Number	312309



Chassis Number	KNALM4149B5031096
Engine Number	
Vehicle Class	Car
Manufacturer	Kia
Model	Cadenza
Model Year	2011
Color	Grey
Mileage	204116 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED,LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.C Doors	FRONT BOTH SIDE ,REAR LEFT SIDE REPAINTED,PORTION REPAIRED	أبواب
02 Lights		الاضاءة
02.A Fog light	NOT WORKING	كشاف الضباب
02.B Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	OK	حالة الجير النظري
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Interior Condition		الحاله الداخليه

DEFECT	REMARKS	
05.A AC Condition	OK	المكيف
05.B Dash Board	CRACKED	لوحة القيادة
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL WET	حالة المحرك النظري
07 Steering Condition		المقود
07.A Steering Oil	MINOR OIL LEAK	زيت المقود
08 Chassis Condition		الشاسي
08.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.