



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|-----------------|
| Site Number | : 756-SHJ AUTO VILLAGE | Plate Code | : |
| Transaction Number | : 19883767 | Plate Category | : |
| Transaction Date | : 02 JUN 2020 10:41:26 | Plate Number | : |
| Queue Number | : 181538 | Import Doc. Ref. | : 19326 EA |
| Chassis Number | : 1N4AL3A92HC219326 | Manufacturer/Model | : NISSAN/ALTIMA |
| Engine Number | : | Model Year | : 2017 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : GREY |
| Service / Indicator | : DSC AUCTION | Mileage | : 44695 |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--|--------|--|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| 17 Shock Absorbers Test | | فحص مخمد الصدمات |
| 17.01 - Shock Absorber Test | Passed | فحص مخمد الصدمات |
| VISUAL TEST: | | |
| 05 Body | | الهيكل |
| 05.02 - Paint | | الصيغ |
| | | BODY PORTION MINOR SCRATCHES |
| 09 Auction | | الفحص الكامل |
| 09.06 - Chassis Ok | OK | الشاصي جيد |
| 09.09 - Engine And Gear Box Performance Ok | OK\ | فحص حالة الماكينة والجير |
| 09.25 - Body Repainted | | أثر صيغ في المركبة |
| | | FRT RHS FENDER,FRT RHS DOOR,RR LHS DOOR, RR LHS FENDER |

The Test Certificate Shows the test Result at the time of inspection only.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط