



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	14 Jan 2022, 11:56:52
Transaction Number	17583442 (CC10006)	Queue Number	312309



Chassis Number	1GT429CG5EF110376
Engine Number	
Vehicle Class	Heavy
Manufacturer	GMC
Model	Sierra
Model Year	2014
Color	White
Mileage	60751 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED	مدكار
01.B Bonnet	REPAINTED	غطاء المحرك
01.C Paint	PORTION REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.D Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS FRAME, FLOOR GETTING RUSTY	صدأ
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
03 Lights		الاضاءة
03.A Head Light	OK	الاضاءة الرئيسية
04 Wipers and Arms		المساحات
04.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرة
05 Engine Condition		المحرك
05.A Engine Condition	OK	حالة المحرك
05.B Mount	BUSHES CRACKED	كرسي

DEFECT	REMARKS	
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Gear Box	OK	الجير
07 Seats Condition		المقاعد
07.A Seat Condition	OK	حالة المقاعد
08 Chassis Condition		الشاسي
08.A Chassis	CHASSIS FRAME COMPLETELY RUSTY & GETTING WEAK,	الشاسيه
09 Suspension System		ممتص الصدمات
09.A Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
09.B Suspension Subframe	SUSPENTION SUB FRAME & CROSS MEMBER GETTING RUSTY	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.