CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2912742
Transaction Date	30 Oct 2026, 15:57:17
Site Name	840 - Emirates Auctions
Transaction Number	75244139 (CC10009) (CC10025)



Vehicle Details

Chassis Number	JN1CA21D0X*******
Specification	GCC Specification
Make	Nissan
Model	Maxima
Model Year	1999
Color	Unknown
Mileage	505742 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	BODY REPAINTED REPAIRED PORTION RUSTY MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR PORTION REPAIRED, RUNNING BOARD ENT RUSTY	الارضية
01.D Pillars	REPAIRED	القوائم
01.E Door Handle &Lock	FRONT LEFT SIDE LOCK MISSING	مقابض الأبواب والأقفال
01.F Sign of front accident	FRONT BUMPER FRAME BULK HEA DFENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.G Vehicle Color	SILVER	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED, EXTENSION END DENT, GETTING RUSTY	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED OIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	REFITTED GETTING RUSTY , NOT CHECKED	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
06 Suspension System		ممتص الصدمات
06.A Arms	BUSHES CRACKED	ازرع
07 Steering Condition		المقود
07.A Steering Oil	OIL LEAK	زيت المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الرودات
08 Interior Condition		الحاله الداخليه
08.A Other	INNER PARTS GETTING RUSTY	اخري
08.B AC Condition	NOT CHECKED	المكيف
08.C Audio	ANTINA MISSING	صوتيات
08.D Steering Wheel and control buttons	WORN OUT/SIDE COVER PORTION MISSING	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae