



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 28 Dec 2021, 17:52:47 |
| Transaction Number | 17760955 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | WMEEJ3BA8DK670594 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Smart |
| Model | |
| Model Year | 2013 |
| Color | Blue |
| Mileage | 54479 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 3 |
| Specification | USA Imported |

| DEFECT | REMARKS | |
|----------------------------------|--|--------------------|
| 01 Chassis Condition | | الشاصي |
| 01.A Chassis | OK | الشاسيه |
| 02 Body | | جسم المركبة |
| 02.A Paint | BODY FIBER PAINT CANNOT CHECK | الصبغ |
| 02.B Floor | UNDER BODY FULLY COVER | الارضية |
| 02.C Pillars | RIGHT SIDE B/PILLAR OUTER REPAIRED,REPAINTED | القوائم |
| 03 Transmission Condition | | الجير |
| 03.A Road Test | NOT CHECK | فحص علي الطريق |
| 03.B Gear Box | SIGN OF OIL WET | الجير |
| 04 Engine Condition | | المحرك |
| 04.A Engine Condition | SHAKING | حالة المحرك |
| 05 Lights | | الاضاءة |
| 05.A Warning Light | WARNING LIGHT ON IN DISPLAY | ضوء تحذير |
| 05.B Brake Light | LEFT SIDE NOT WORKING | نور الفرامل |
| 05.C Indicator & Hazard light | REAR LEFT SIDE NOT WORKING | الاشارات |

| DEFECT | REMARKS | |
|------------------------------------|---|------------------------|
| 05.D Head Light | LEFT SIDE LOW BEAM NOT WORKING | الاضاءة الرئيسية |
| 05.E Tail Light | FRONT PARK LIGHT NOT WORKING | الانارة |
| 06 Wipers and Arms | | المساحات |
| 06.A Wiper Arm &Blade | WORN OUT | ازرع المساحات والشفرات |
| 07 Seats Condition | | المقاعد |
| 07.A Seat Belt | OK | حزام الأمان |
| 07.B Seat Condition | OK | حالة المقاعد |
| 08 Tires and Rims Condition | | الاطارات |
| 08.A Front Tyre | BOTH SIDE 2008 & EXPIRED,CRACKED,STUDLESS | الاطار الامامي |
| 08.B Rear Tyre | BOTH SIDE 2013 EXPIRED,CRACKED,STUDLESS | الاطار الخلفي |
| 08.C Rims Condition | FRONT LEFT SIDE BEND ,RIMS GETTING RUSTY | حالة الجنوط |
| 09 Interior Condition | | الحالة الداخليه |
| 09.A AC Condition | NOT WORKING | المكيف |
| 09.B Mirror | RIGHT SIDE GLASS BROKEN | المرابا |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.