

Queue Number 2707035

Transaction Date 07 Sep 2026, 13:00:57

Site Name
840 - Emirates AuctionsTransaction Number
52142373 (CC10021) (CC10021)

Vehicle Details

Chassis Number	WBANU11038*****
Specification	GCC Specification
Make	BMW
Model	523i
Model Year	2008
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		
		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORION REPAIRED,MINOR DENTS SCRATCHES,PORION FADED RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY	الارضية
01.D Bumper	MISALIGN,PORION DAMAGED	دعامية
01.E Door Handle & Lock	FRONT LEFT SIDE OUTER HANDLE DAMAGED	مقابض الأبواب والأقفال
02 Chassis Condition		
		الشاسي
02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		
		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,PARTS REFITTED MINOR OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		
		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,PARTS REFITTED MINOR OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		
		الاطارات
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنايبير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخرى
09.B AC Condition	NOT CHECK	المكيف
09.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.D Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae