



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **13 May 2022, 11:52:12**
 Transaction Number **86984488 (CC10006)** Queue Number **312309**



Chassis Number **JHLRE48399C401303**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Honda**
 Model **CRV**
 Model Year **2009**
 Color **Black**
 Mileage **494576 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE PORTION REPAIRED,REPAINTED	مدكار
01.B Bonnet	REPAINTED	غطاء المحرك
01.C Paint	BODY PORTION REPAIRED,REPAINTED & MINOR DENT SCRATCHES	الصبغ
01.D Roof	REPAINTED	السقف
02 Engine Condition		المحرك
02.A Other	RPM NOT WORKING PROPERLY	اخرى
02.B Visual Engine Condition	REFITTED	حالة المحرك النظري
02.C Mount	MOUNT RUBBER CUT	كرسي
03 Suspension System		ممتص الصدمات
03.A Other	STABILIZER LINK BOOT CUT	اخرى
03.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
04 Steering Condition		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الروداد
04.B Steering Box	POWER STEERING LEAKING	جهاز المقود
04.C Steering Oil	OIL LEAK	زيت المقود

DEFECT	REMARKS	
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
06 Chassis Condition		الشاسي
06.A Chassis	OK	الشاسيه
07 Lights		الاضاءة
07.A Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Visual Gear Box Condition	OK	حالة الجير النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.