



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **15 May 2023, 12:05:59**  
 Transaction Number **75698743 (CC10006)** Queue Number **716171**



Chassis Number **RKLBC42E4C4515583**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Toyota**  
 Model **Corolla**  
 Model Year **2012**  
 Color **--**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Lights</b>		<b>الاضاءة</b>
01.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Sign of front accident		وجود مؤشر لحادث في المقدمة
02.B Vehicle Color	GRAY	لون المركبة
02.C Bumper	MISALIGN PORTION DAMAGED	دعامة
02.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED ,PORTION RUSTY	الصبغ
02.E Other	FRONT FENDER FRAME, BUMPER FRAME, RADITOR SUPPORT, BULK HEAD REPAIRED	اخرى
02.F Floor	UNDER BODY RUST PROOFED, PORTION DENT	الارضية
02.G Windshield	FRONT SPOT CRACK	زجاج
<b>03 Suspension System</b>		<b>ممتص الصدمات</b>
03.A Arms	FRONT&REAR LOWER ARM BUSHES CRACKED	ازرع
03.B Ball Joint	BOOT CUT	مفصل كروي
<b>04 Chassis Condition</b>		<b>الشاسي</b>
04.A Chassis	FRONT RIGHT SIDE CHASSIS END REPAIRED	الشاسيه

DEFECT	REMARKS	
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>06 Interior Condition</b>		<b>الحالة الداخليه</b>
06.A AC Condition	NOT CHECKED	المكيف
06.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
06.C Odometer reading	NOT CHECKED	قراءة عداد المسافات
06.D Dash Board	PORTION CRACKED	لوحة القيادة
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK ,REFITTED	حالة المحرك النظرى
07.B Mount	BUSHES CRACKED	كرسي
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Rear Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الخلفي
08.B Front Tyre	BOTH SIDE 2019 CRACKED ,	الاطار الامامي
<b>09 Transmission Condition</b>		<b>الجير</b>
09.A Visual Gear Box Condition	NOT CHECKED ,OIL LEAK ,REFITTED	حالة الجير النظرى
09.B Road Test	NOT CHECKED	فحص علي الطريق
09.C Gear Box Mount	BUSH CRACK	كرسي الجير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.