CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2949192
Transaction Date	06 Nov 2026, 16:19:15
Site Name	840 - Emirates Auctions
Transaction Number	56168466 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1N4AA5AP1D*******
Specification	GCC Specification
Make	Nissan
Model	Maxima
Model Year	2013
Color	White
Mileage	167874 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED,RUSTY	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY , RUST PROOFED	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY THICK RUST PROOFED,NOT VISIBLE	الارضية
01.F Bumper	MISALIGN,COVER HOOK MISSING	دعامية
01.G Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD REAPIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED, FRONT RIGHT SIDE SLIGHTLY BEND	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY SHAKING	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Tail Light	RIGHT SIDE CRACKED	الضوء الخلفي
06.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
07.B Other	SUSPENSION RUST PROOFED	اخري
07.C Ball Joint	BOT CUT	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A Other	INETRIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	NOT COOLING	المكيف
08.C Power Window Switch And Glass	REAR LEFT SIDE NOT WORKING	مفتاح النافذه و الزجاج
08.D Dash Board	PORTION MELTED GOLVE BOX DAMAGED	لوحة القياده
08.E Sun Visor	RIGHT SIDE DAMAGED	حاجب الشمس
08.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae