CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906042
Transaction Date	30 Oct 2026, 14:54:01
Site Name	840 - Emirates Auctions
Transaction Number	74012239 (CC10010) (CC10011)



Vehicle Details

Chassis Number	5KBRL6864K*******
Specification	GCC Specification
Make	Honda
Model	Odyssey
Model Year	2019
Color	Green
Mileage	336966 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION RUSTY FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	MISALIGN ,SCRATCHES . PORTION CRACKED	دعامية
01.E Trunk	AUTO NOT WORKING.	صندوق
01.F Vehicle Color	GRAY.	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY,PARTS REFITTED .	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	MIDDLE ROW SEATS MISSING ,FRONT SEAT PORTION CUT . FRONT RIGHT SIDE ADJUSTMENT SWITCH DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2025.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 DRY CRACKED.	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	LENS FADED.	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACKED.	الضوء الخلفي
07.C Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
08 Brake Condition		**الفرامل**
08.A Brake Pedal	SPONGY.	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		**ممتص الصدمات**
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED.	ازرع
10 Interior Condition		**الحاله الداخليه**
10.A Other	INTERIOR PARTS RUSTY .	اخري
10.B Mirror	RIGHT SIDE FODING NOT WORKING.	المرايا
10.C AC Condition	OK	المكيف
10.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT/HARD	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae