

Queue Number 2830693

Transaction Date 05 Oct 2026, 15:45:25

Site Name
840 - Emirates AuctionsTransaction Number
39975803 (CC10013) (CC10011)

Vehicle Details

Chassis Number	5XXP581C2M*****
Specification	GCC Specification
Make	Kia
Model	Telluride
Model Year	2021
Color	Unknown
Mileage	121690 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAIRED REPAINTED,REAR BOTH REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED REPAIRED,REAR LEFT REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED MINOR DENT	الارضية
01.F Bumper	MISALIGN,LOGO GETTING FADED	دعامية
01.G Vehicle Color	SILVER	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUTSY	الحالة النظرية للجير
--------------------------------	---	----------------------

04.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2023 LEFT SIDE TIRE FUNCTURE , CRACK GETTING WORN OUT	الاطار الامامي
-----------------	---	----------------

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LEFT SIDE GETTING FADED	الاضاءة الرئيسية
06.B Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك وطنايبر الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	الزرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	CENTER MIRROR PORTIO LOOSE	المرايا
10.C AC Condition	OK	المكيف
10.D Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
10.E Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae