



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Jul 2022, 11:46:04
Transaction Number	42916398 (CC10006)	Queue Number	312309



Chassis Number	WAUAHCFC6FN007883
Engine Number	
Vehicle Class	Car
Manufacturer	Audi
Model	A6
Model Year	2015
Color	Black
Mileage	165588 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Lights</b>		الاضاءة
01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
<b>02 Body</b>		جسم المركبة
02.A Paint	BODY PORTON REPAIRED REPAINTED MINOR DENTS SCRATCHES	الصبغ
02.B Floor	UNDER FLOOR FENDER CHASSIS FRAME FULLY COVERED CHECKED VISIBLE AREA OK	الارضية
02.C Fenders	REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
<b>03 Interior Condition</b>		الحاله الداخليه
03.A AC Condition	OK	المكيف
03.B Roof Ceiling	LOOSE	بطانه السقف
<b>04 Chassis Condition</b>		الشاصي
04.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>05 Tires and Rims Condition</b>		الاطارات
05.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي

DEFECT	REMARKS	
05.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Visual Gear Box Condition	SIGN OF LEAK	حالة الجير النظري
07.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Arms	LOWER ARM BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
<b>09 Steering Condition</b>		<b>المقود</b>
09.A Tie Rod End	BOOT CUT	مؤخرة الروداد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.