



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20081160	Plate Category	: PRIVATE
Transaction Date	: 29 JUN 2020 10:41:47	Plate Number	: 980764 EA
Queue Number	: 190631	Import Doc. Ref.	:
Chassis Number	: KMHJM81D69U980764	Manufacturer/Model	: HYUNDAI/TUCSON
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفرامل
13.04 - Brake Test	Passed		فحص الفرامل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
VISUAL TEST:			
01 Lights			الانوار
01.04 - Head Lights		LENS FADED	الانوار الامامية
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		DOT 0119-1016	الاطارات الامامية
04.07 - Rims		CENTER CAP MISSING	الرنجات
05 Body			الهيكل
05.02 - Paint		DENT/SCRATCHES	الصبغ
05.07 - Floor		PARTLY RUSTY	الارضية
06 General Items			الاشياء العامة
06.08 - Interior Lights		INTERIOR LIGHT SWICHT PANEL BROKEN/DAMAGED	الانوار الداخلية
06.14 - Transmission Condition		SHIFT SHOCK & DELAY CHANGE GEAR	حالة ناقل الحركة
06.16 - Engine Condition, Smoke		OK	حالة المحرك - الدخان
07 Remarks			ملاحظات
07.04 - Others		132319 KM	ملاحظات اخرى
09 Auction			الفحص الكامل
09.06 - Chassis Ok		OK	الشاصي جيد
09.20 - Differential Not Ok		FRONT DIFFIRENTIAL OIL LEAK	عطل في الدفرنش

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.