CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2945033 |
| Transaction Date | 07 Nov 2026, 12:40:09 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 40774087 (CC10013) (CC10013) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | MNCBS32727******* |
| Specification | GCC Specification |
| Make | Ford |
| Model | Ranger |
| Model Year | 2007 |
| Color | White |
| Mileage | 433056 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY | الصبغ |
| 01.B Rusty | UNDER BODY PARTS , SUSPENTION GETTING RUSTY | صدأ |
| 01.C Floor | UNDER FLOOR PORTION DENTS, MUDDY | الارضية |
| 01.D Bumper | MISALIGN, PORTION DAMAGED LOGO MISSING | دعامية |
| 01.E Other | LOADING CABIN EXTRA BAR FITTING | اخري |
| 01.F Trunk | TAIL GATE HANDLE DAMAGED | صندوق |
| 01.G Fuel Tank | DENT | خزان الوقود |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | FRONT BOTH SIDE CHASSIS FRAME MOUNT BRACKET CRACKED GETTING RUSTY | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Mount | MOUNT RUBBER DRY CRACK | كرسي |
| 03.B Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY | الحالة النظريه للمحرك |
| **04 Exhaust System** | | نظام العادم |
| 04.A Other | DENT | اخري |
| **05 Transmission Condition** | | الجير |

| Condition | Remarks | الحالة |
|---|---|---|
| 05.A Gear Box Visual Condition | NOT CHECKED REFITTED OIL LEAK PARTS RUSTY | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECKED | فحص علي الطريق |
| **06 Lights** | | الاضاءة |
| 06.A Head Light | LENS FADED, ALL LIGHTS NOT CHECKED / BRACKET DAMAGED | الاضاءة الرئيسية |
| **07 Suspension System** | | ممتص الصدمات |
| 07.A Leaf Spring | MISALIGN , BUSHES DRY CRACK | |
| 07.B Other | ALL BUSHES DRY CRACK CUT | اخري |
| **08 Interior Condition** | | الحاله الداخليه |
| 08.A Other | INTERIOR PARTS RUSTY,SIGN OF FLOODED | اخري |
| 08.B AC Condition | NOT CHECKED | المكيف |
| 08.C Dash Board | GETTING FADED PORTION WORN OUT CRACK | لوحة القياده |
| 08.D Roof Ceiling | PORTION WORN OUT | بطانه السقف |
| 08.E Sun Visor | LOOSE | حاجب الشمس |
| 08.F Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 08.G Gear Shifting Lever | KNOB & DUST COVER WORN OUT CRACK | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**