

Queue Number 2618293

Transaction Date 04 Aug 2026, 16:23:39

Site Name
840 - Emirates AuctionsTransaction Number
83288520 (CC10010) (CC10010)

Vehicle Details

Chassis Number	WDCFF5KE4L*****
Specification	GCC Specification
Make	Mercedes
Model	GLS 450
Model Year	2020
Color	--
Mileage	97008 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED ,MINOR DENT SCRATCHES	الصيغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA .	الارضية
01.D Bumper	MISALIGN PORTION SCRATCHES	دعامية
01.E Other	POWERTRAIN UNDER BODY SUSPENSION RUNNIG PARTS RUSTY ,SIGN OF FLOODED.	اخرى
01.F Sign of front accident	FRONT BULKHEAD FENDER INNER FRAME RADIATOR SUPPORT REPAIRED ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.G Vehicle Color	RED	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED , MUDDY ,COMPLETE COVERED .	الشاسيه
02.B Other	NEED TO REMOVE FRONT BOTH SIDE FENDER COVER UNDER COVER FOR PROPER INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Other	TURBO CHARGER PIPE WELDFED REPAIRED. mild-hybrid system (EQ Boost)	اخرى
03.B Engine Visual Condition	REFITTED COMPONENT PARTS RUSTY.	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK , DRIVER SEAT PORTION LOOSE	حالة المقاعد
---------------------	---	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED COMPONENT PARTS RUSTY ,GET JERKING.	الحالة النظرية للجير
05.B Propeller Shaft	REFITTED .	ناقل الحركة
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطناير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES DRY CRACKED .	ازرع
09 Interior Condition		الحالة الداخليه
09.A AC Condition	OK	المكيف
09.B Power Window Switch And Glass	REAR RIGHT SIDE SWITCH DAMAGED	مفتاح النافذه و الزجاج
09.C Dash Board	LEATHER REPLACED	لوحة القيادة
09.D Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
09.E Engine Start Button	SWITCH GETTING FADED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae