

Queue Number 2706969

Transaction Date 04 Sep 2026, 12:49:41

Site Name  
840 - Emirates AuctionsTransaction Number  
74944782 (CC10021) (CC10021)

## Vehicle Details

|                   |                 |
|-------------------|-----------------|
| Chassis Number    | 1N4AA6AV4K***** |
| Specification     | Imported        |
| Make              | Nissan          |
| Model             | Maxima          |
| Model Year        | 2019            |
| Color             | White           |
| Mileage           | 70084 Miles     |
| Fuel Type         | Petrol          |
| Transmission Type |                 |
| No. Of Cylinders  | 6               |

## Condition

## Remarks

## الحالة

## 01 Body

## جسم المركبة

|                             |                                                                                   |                            |
|-----------------------------|-----------------------------------------------------------------------------------|----------------------------|
| 01.A Paint                  | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY | الصبغ                      |
| 01.B Rusty                  | UNDER BODY PARTS,SUSPENSION GETTING RUSTY                                         | صدأ                        |
| 01.C Floor                  | UNDER FLOOR PORTION DENT ,MUDDY                                                   | الارضية                    |
| 01.D Bumper                 | MISALIGN,PORTION DAMAGED                                                          | دعامية                     |
| 01.E Sign of front accident | FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD INNER FENDER FRAME REPAIRED.      | وجود مؤشر لحادث في المقدمة |

## 02 Chassis Condition

## الشاسي

|              |                                                                                            |         |
|--------------|--------------------------------------------------------------------------------------------|---------|
| 02.A Chassis | CHASSIS COVERED,MUDDY,FRONT RIGHT SIDE CHASSIS ALIGN,DENT                                  | الشاسيه |
| 02.B Other   | CHASSIS COVERED,NEED TO REMOVE BOTH SIDE FENDER & UNDER ENGINE COVER FOR PROPER INSPECTION | اخرى    |

## 03 Engine Condition

## المحرك

|                              |                                                       |                       |
|------------------------------|-------------------------------------------------------|-----------------------|
| 03.A Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,PARTS RUSTY | الحالة النظرية للمحرك |
|------------------------------|-------------------------------------------------------|-----------------------|

## 04 Transmission Condition

## الجير

|                                |                          |                      |
|--------------------------------|--------------------------|----------------------|
| 04.A Gear Box Visual Condition | NOT CHECKED ,PARTS RUSTY | الحالة النظرية للجير |
| 04.B Road Test                 | NOT CHECKED ,PARTS RUSTY | فحص علي الطريق       |

## 05 Tires and Rims Condition

## الاطارات

| Condition                               | Remarks                                          | الحالة                     |
|-----------------------------------------|--------------------------------------------------|----------------------------|
| 05.A Front Tyre                         | BOTH SIDE CRACK                                  | الاطار الامامي             |
| 05.B Rear Tyre                          | BOTH SIDE CRACK                                  | الاطار الخلفي              |
| 05.C Rims Condition                     | MINOR DENT SCRATCHES                             | حالة الجنوط                |
| <b>06 Lights</b>                        |                                                  | <b>الاضاءة</b>             |
| 06.A Head Light                         | LENS FADED, ALL LIGHTS NOT CHECK                 | الاضاءة الرئيسية           |
| <b>07 Brake Condition</b>               |                                                  | <b>الفرامل</b>             |
| 07.A Disc&Drum                          | RUSTY                                            | دسك و طنابير الفرامل       |
| <b>08 Suspension System</b>             |                                                  | <b>ممتص الصدمات</b>        |
| 08.A Arms                               | BUSHES CRACK                                     | ازرع                       |
| 08.B Ball Joint                         | BOOT CUT                                         | مفصل كروي                  |
| <b>09 Interior Condition</b>            |                                                  | <b>الحالة الداخلية</b>     |
| 09.A Other                              | INTERIOR PARTS GETTING RUSTY , ( WATER FLOODED ) | اخرى                       |
| 09.B AC Condition                       | NOT CHECK                                        | المكيف                     |
| 09.C Door Panel                         | PORTION DAMAGED                                  | لوحة بطانة الباب           |
| 09.D Steering Wheel and control buttons | WORN OUT                                         | عجلة القيادة وازرار التحكم |
| 09.E Gear Shifting Lever                | WORN OUT                                         | ذراع نقل السرعات           |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](http://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](http://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

للشكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)