



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	04 Dec 2022, 17:15:26
Transaction Number	95082231 (CC10009)	Queue Number	635611



Chassis Number	JTMHU09J185007508
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser
Model Year	2008
Color	Black
Mileage	420188 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Gear Box Mount	MOUNT CRACK	كرسي الجير
01.C Visual Gear Box Condition	JERKING, MINOR OIL LEAK	حالة الجير النظري
02 Interior Condition		الحاله الداخليه
02.A AC Condition	NOT COOLING	المكيف
02.B Steering Wheel and control buttons	DAMAGED	عجلة القيادة وازرار التحكم
02.C Power Window Switch	FROM MAIN SWITCH LOOSE	مفتاح النافذه
03 Steering Condition		المقود
03.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2020/2018	الاطار الامامي
05 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
05.A Ball Joint	BOOT CUT	مفصل كروي
05.B Arms	LOWER ARM BUSHES CRACKED	ازرع
05.C Shock Absorber	LEAK	ممتص الصدمات
06 Body		جسم المركبة
06.A Paint	BODY PORTION REPAIRED REPAINTED ,MINOR DENT SCRATCHES	الصبغ
06.B Roof	PORTION HOLE	السقف
06.C Floor	MIDDLE BOTH SIDE MOUNT RUSTY WEAK /UNDER FLOOR RUSTY PROOFED	الارضية
07 Engine Condition		المحرك
07.A Mount	MOUNT CRACK	كرسي
07.B Visual Engine Condition	MINOR OIL LEAK .	حالة المحرك النظرى
08 Lights		الاضاءة
08.A Head Light	HIGH BEAM NOT WORKING	الاضاءة الرئيسية
08.B Indicator & Hazard light	FRONT RIGHT SIDE NOT WORKING	الاشارات
09 Chassis Condition		الشاسي
09.A Chassis	FRONT BOTH SIDE CHASSIS INNER MINOR RUSTY BULGED ,THICK RUST PROOFED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.