CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934049
Transaction Date	04 Nov 2026, 09:53:06
Site Name	840 - Emirates Auctions
Transaction Number	74948326 (CC10010) (CC10010)



Vehicle Details

Chassis Number	1C4HJXDG8J*******
Specification	GCC Specification
Make	Jeep
Model	Wrangler
Model Year	2018
Color	Silver
Mileage	101628 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED REPAINTED , REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY,	الصبغ
01.C Doors	RIGHT SIDE REPAINTED REPAIRED BOTH REFITTED .	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bonnet	REFITTED REPAINTED ,STAY STICK MISSING.	غطاء المحرك
01.G Pillars	RIGHT SIDE DOOR PILLAR ROCKER PANEL RUNNING BOARD REPAIRED.	القوائم
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	BOTH SIDE CHASSIS REPAIRED BEND ,CHASSIS GETTING RUSTY.	الشاسيه
02.B Chassis Number	VIN AREA GETTING RUSTY .	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS REFITTED OIL LEAK COMPONENT PARTS RUSTY, ABNORMAL NOISY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED.	فحص علي الطريق
04.C Four Wheel Drive	NOT CHECKED.	الدفع الرباعي
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2020 EXPIRED DAMAGED .,	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020 EXPIRED CRACKED.	الاطار الخلفي
05.C Spare Tire &Tools	MISSING.	الاطار الاحتياطي و العدة
06 Lights		**الاضاءة**
06.A Warning Light	EXTRA WARNING LIGHT /WARNING MESSAGE ON IN CLUSTER.	ضوء تحذير
07 Brake Condition		**الفرامل**
07.A Brake Pedal	HARD WEAK ,ABS NOT WORKING.	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		**ممتص الصدمات**
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
08.C Stabilizer Bar And Link Rod	BUSHES CRACKED .	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		**المقود**
09.A Steering Box	HARD	جهاز المقود
10 Interior Condition		**الحاله الداخليه**
10.A Other	INTERIOR PARTS GETTING RUSTY.	اخري
10.B AC Condition	NOT WORKING PROPERLY .	المكيف
10.C Dash Board	GLOVE BOX DAMAGED	لوحة القياده
10.D Sun Visor	LEFT SIDE LOCK DAMAGED REMOVED	حاجب الشمس
10.E Door Panel	WORNOUT PORTION LOOSE	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT.,	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae